State of California — The Resources Agency DEPARTMENT OF PARKS AND RECREATION PRIMARY RECORD	Primary #: HRI # Trinomial NRHP Status Code: Other Listings Review Code Reviewer Date			
story entry vestibule and one-story shed roof L compose the fr finished with a plain facia and have exposed rafters. The prim double doors with applied panels and a Gothic transom which	hly rectangular plan. The primary roof is gabled. A one and one-half ont façade of the building. Gable ends on the primary roof and entry are ary gable end is clad with fish scale shingles. The entry vestibule has fills the space under the gable. This treatment makes the entry the tair provides access. The building is clad with clapboard and exhibits			
*P3b. Resource Attributes: HP16 *P4. Resources Present: ■ Building □ Structure □ P5b. Description of Photo: Front façade, view south *P6. Date Constructed/Age: 1882	Object ☐ Site ☐ District ■ Element of District ☐ Prehistoric ■Historic ☐ Both			
P5. Photograph or Drawing (Photograph required for build and objects.)	*P7. Owner and Address:			

State	of Califor	nia —	-The I	Resou	ırces	Agency	1
DEPA	RTMENT	OF P	ARKS	AND	RECI	REATION	i.

Primary #: HRI#:

BUILDING, STRUCTURE, AND OBJECT RECORD

*Resource Identifier: 932 West J Street *NRHP Status Code: 3D Historic Name: N/A B1. Common Name: same B2. B3. Original Use: Religious B4. Present Use: Commercial *B5. Architectural Style: Vernacular Construction History: Constructed 1882. The single-story shed roof portion of the building adjacent to the entry may be a *B6. latter addition. Date: N/A Original Location: same Moved? ■ No ☐ Yes ☐ Unknown *B7. Related Features: *B8. B9b. Builder: unknown B9a. Architect: unknown Period of Significance: 1847-1940 *B10. Significance: Theme: Benicia Downtown District

This is a good example of a simple Vernacular church building of frame construction. The patching of the front primary gable indicates that at some time in the past the entry to the building may have been changed. This might be researched further in photographic collections. The building retains its integrity of materials, workmanship, setting and location as well as its over-all design. It is no longer used for religious purposes, but its conversion to a commercial use has not resulted in exterior alteration. The church is directly related to the Rectory at the rear which faces onto West Second Street. The two buildings should be considered together in regard to issues of eligibility and for purposes of project review. The building is a designated Landmark and contributes to the Downtown Historic District. The building was recorded by HABS in 1977.

Applicable Criteria: A / C

B11. Additional Resource Attributes: N/A

Property Type: Religious

B12. References: McAlester, Virginia and Lee. A Field Guide to American Houses. New York: Alfred Knopf (1986); Bruegmann, Robert. Benicia Portrait of an Early California Town: An Architectural History (San Francisco: 101 Productions (1980); Woodbridge, Sally and Cannon Design Group. Benicia, California: Downtown Historic Conservation Plan. City of Benicia, 1990; Sanborn Map Benicia, CA. 1886; 1986 Benicia Historic Inventory form.

BUILDING, STRUCTURE, AND OBJECT RECORD


Remarks: N/A

B14. Evaluator: Carol Roland, Ph.D.

Roland-Nawi Associates: Preservation Consultants

4829 Crestwood Way Sacramento, CA 95822

B 15. Date of Evaluation: 11-22-04




(This space reserved for official comments.)

CONTINUATION SHEET

Resource Identifier: 190 West J Street

X Continuation O Update



HABS photograph 1977